**FIG. 1**




FIG. 3B





FIG. 2

**FIG. 3A**




FIG. 4




FIG. 5A





FIG. 5B



WIRING DIAGRAM
OVERMOLD NOT SHOWN FOR CLARITY

FIG. 6A




FIG. 6B





FIG. 7






FIG. 9B

FIG. 9A




FIG. 9C